Freedom of Information (FOI) Request Reference: FOI-731005534



the play inspection company

Annual Inspection

Government of Jersey

Longbeach Play Area

La Rue a Don, Grouville, JE3 9DY





Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL t- 01202 590675 e- info@playinspections.co.uk

www. playinspections .co.uk







Inspection Scope for RPII Inspection Methodology

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to BS EN 1176. We have not assessed these against the requirements of BS EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

- BS EN 15312 Free access multi-sports equipment
- BS EN 14974 Skateparks
- BS EN 16630 Permanently installed outdoor fitness equipment
- BS EN 16899 Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism.

Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

Freedom of Information (FOI) Request Reference: FOI-731005534

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

A full copy of the Play Inspection Company Ltd. Terms & Conditions is available on our website (www.playinspections.co.uk)

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	\checkmark	V [1]
6.1 d) Overall levels of safety of foundations (see note 1)	\checkmark	V [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	\checkmark	V [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	V	V [3]
6.1 d) Effects of weather	\checkmark	
6.1 d) Presence of rot, decay or corrosion (see note 1)	\checkmark	V [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	\checkmark	[4]
6.1 d) Excavation or dismantling/additional measures	\checkmark	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	\checkmark	(5]
6.2.1 Inspection of one post equipment (see note 1)	\checkmark	V [1]
6.2.4 Undertaking the Operators inspection protocol	\checkmark	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

© The Play Inspection Company & the Register of Play Inspectors International 15th September 2021

Freedom of Information (FOI) Request Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Seve			x Severity		
	1	1			Sev	erity>>		
	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
Likelihood	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
				Very Low	Low	Moderate	High	Very High
	THE PLAN			1	2	3	4	5
	PI ANAGHOOM			No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality
						Severity>>		
Note 1: The total risk scores included within our reports are a multiplication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity								

(3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Equipment has been assessed to the following standards where relevant:

BS EN 1176 Parts 1-11 (Playground equipment and surfacing)

BS EN 14974 (Facilities for users of roller sports equipment)

BS EN 15312 (Free access multi-sports equipment)

BS EN 16899 (Parkour Equipment)

BS EN 16630 (Outdoor Fitness Equipment).



Longbeach Play Area

Inspection Ref: 2500133

Site Ref: 91223

Inspected: 1-October-2024 - 12:55 by

(RPII Annual Inspector)

Risk Assessment: 12 Moderate Risk



Location:

The site is located in an area of public open space and is overlooked by a number of properties in the local community. **Disabled Access:**

Severely limited access - an area that presents serious barriers to disabled people, even when skilled help is at hand.



6 - Low Risk		
Item:	Site General	
Manufacturer:	Owner/Operator	
Surface Type:	N/A	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	5	
Finding 1		Finding 2
There is some tree debris on maintain	the surfacing - Remove and	The sea is in close proximity to the playground. Risk assessment of this is a specialist field and outside the scope of our inspection Contact our official water safety partner the RLSS (Royal Life Saving Society) at www.rlss.org.uk and / or ensure that the appropriate risk assessment is in place
Finding 3		Finding 4
	erson at appropriate intervals to	There is excess grease on the shackles - Clean and maintain
Finding 5		
It is recommended that signage, with information including the site address, contact information for maintenance issues and emergency contact details are provided for the facility - Provide in accordance with the recommendations		



Item:	Sign	
Manufacturer:	Not Identified	
Surface Type:	Sand	
Item Quantity:	1	
Equipment Compliance:	N/A	Children's play area
Surface Area Compliance:	N/A	play area Please do not take dogs into take dogs into take dogs into
Total Findings:	3	
Finding 1		Finding 2
There are projecting screw ends present - Remove and provide more appropriate fixings if required		The surface has eroded and the foundations are exposed - Reinstate surrounding surfaces to cover the foundations
provide more appropriate lix	ings in required	remotive currenting curraces to cover the reundatione
· · · ·		
	- ·	
Finding 3	- ·	
Finding 3	- ·	
Finding 3 The sign is peeling - Replace	- ·	
Finding 3 The sign is peeling - Replace 4 - Very Low Risk Item:	e as required	
Finding 3 The sign is peeling - Replace 4 - Very Low Risk Item: Manufacturer:	e as required	
Finding 3 The sign is peeling - Replace 4 - Very Low Risk Item: Manufacturer: Surface Type:	e as required Sign Not Identified	
Finding 3 The sign is peeling - Replace	e as required Sign Not Identified	

Total Findings:

Finding 1

This item is satisfactory - no work required -

1



😜 8 - Low Risk

Item:	Litter Bin	
Manufacturer:	Not Identified	
Surface Type:	Decking	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings	1	Carlos A Carlos
Total Findings:	1	

Finding 1

The bin is not securely fixed to the surface and there is some possibility of the item tipping or rolling over - Secure the bin to the ground

6 - Low Risk		
Item: Manufacturer: Surface Type: Item Quantity:	Bench Not Identified Sand 6	
Equipment Compliance: Surface Area Compliance:	N/A N/A	
Total Findings:	2	
Finding 1		Finding 2
The surface has eroded and	the foundations are exposed -	A number of fixing(s) have worked loose - Secure all loose

fixings

Reinstate surrounding surfaces to cover the foundations



Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	Fence Not Identified Sand 1 N/A N/A 2	
Finding 1		Finding 2
There are head / neck entrap on the top of the fence - Con	ments between the projections sider removal of the	There are a number of loose posts around the fence - Monitor for any further deterioration and reset as required



12 - Moderate Risk			
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	Single Point Swing - Type 3 Not Identified Sand 1 No Yes		
Finding 1 The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work recommended		Finding 2 There is some notable evidence of connecting link wear - Monitor for any further deterioration and replace when 40% worn	
Finding 3		Finding 4	
There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn		The bushes are worn or missing - Replace worn or missing bushes	
Finding 5		Finding 6	
in the event of a catastrophic is internal, the equipment is a highly dynamic nature, we wa	a failure, however as the failsafe of some age and also due to its ould recommend that the item cement provided as necessary.	There are sharp projections on the split pins - Remove projections	
Finding 7		Finding 8	
The swing seat connectors h Monitor for further deteriorati worn		The adjacent foliage is overgrowing the falling space - Cut back and maintain	



8 - Low Risk		
Item:	1 Bay 3 Seat (Cradle)	
Manufacturer:	Record RSS	
Surface Type:	Sand	
Item Quantity:	1	
Equipment Compliance:	No	
Surface Area Compliance:	Yes	
Total Findings:	7	
Finding 1		Finding 2
The frame is bent - Monitor for any further deterioration and replace when worn		The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work recommended
Finding 3		Finding 4
There are caps missing from Replace missing caps under		There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn
Finding 5		Finding 6
The seats are too close to each other as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended		The seats are too close to the frame as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended
Finding 7		
	in a single bay in contravention and remove the middle swing	



-	8 - Low Risk	
1	8 - Low Risk	

ltem: Manufacturer:	1 Bay 3 Seat (Flat) Record RSS	
Surface Type:	Sand	
Item Quantity:	1	
Equipment Compliance:	Νο	
Surface Area Compliance:	Yes	
Total Findings:	5	
Finding 1		Finding 2
	in a single bay in contravention and remove the middle swing	The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work recommended

li required	recommended
Finding 3	Finding 4
There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn	The seats are too close to the frame as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action
	is required - Monitor - No remedial work recommended

Finding 5

The seats are too close to each other as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Consider removing the middle seat

Item:	Wooden Animal	
Manufacturer:	Not Identified	
Surface Type:	Sand	
Item Quantity:	1	and the lot Frank State
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	A Provide States of the second s

Finding 1

The bench forms a projecting obstacle / hard object within the falling space of the equipment, in contravention of the requirements of BS EN 1176 Part 1 - Monitor - No remedial work recommended



12 - Moderate Risk				
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	Multi Play (Junior) Not Identified Sand 1 No No			
Finding 1		Finding 2		
The large rocks / firepit forms a projecting obstacle / hard object within the falling space of the equipment, in contravention of the requirements of BS EN 1176 Part 1 - Remove all stones, rocks and other debris from the falling space of the equipment		There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required		
Finding 3		Finding 4		
This item has no slide bar fitted as required by BS EN 1176 Part 3 - Monitor - No remedial work recommended		There is/are inserts missing - Replace missing inserts		
Finding 5		Finding 6		
There is or are fixings missing on the item - Replace all missing fixings		The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps - Monitor - No remedial work recommended		
Finding 7		Finding 8		
The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint		The fixings have corroded excessively - Replace all		
Finding 9		Finding 10		
There is an opening in the barriers exceeding the width allowed (500mm) in BS EN 1176, and no guardrail has been provided; this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended		There are falls in excess of 600mm between adjacent		
Finding 11		Finding 12		
The vegetation forms a hard object within the falling space of the equipment and there is also insufficient surfacing provided in contravention of BS EN 1176 Part 1 - Monitor - no remedial work recommended		A number of fixing(s) have worked loose - Secure all loose fixings		
Finding 13		Finding 14		
There are areas or parts of the have rotted - Replace all affe	ne timber on the structure that cted timbers	There is/are finger entrapment/s in the framework and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Replace missing inserts to remove entrapments		



Finding 15	Finding 16	
The design of the barrier does not prevent a user from passing underneath in contravention of the requirements of BS EN 1176 Part 1 - Monitor use and provide a compliant barrier as required	There is insufficient guarding on the steps leading up to the platform that exceeds 1m in height which contravenes the requirements on BS EN 1176 Part 1 - Monitor - No remedial work recommended	
Finding 17		
There is a split in the slide support - Repair item	-	



Findings information










6 - Low Risk (Finding 4)

Item:

Ancillary Items - Site General Owner/Operator

Risk Level:

L - Low Risk N/A



Finding: There is excess grease on the shackles

Action: Clean and maintain

5 - Very Low Risk (Finding 5) Ancillary Items - Site General Risk Level: V - Very Low Risk Item: Owner/Operator Surface: N/A Manufacturer: **NO IMAGE APPLICABLE** Finding: It is recommended that signage, with information Action: Provide in accordance with the recommendations including the site address, contact information for

maintenance issues and emergency contact details are

provided for the facility



6 - Low Risk (Finding 1)






Finding: The surface has eroded and the foundations are exposed

Action: Reinstate surrounding surfaces to cover the foundations








6 - Very Lo	w Risk (Finding 1)			
ltem: Manufacturer:	Ancillary Items - Bench Not Identified	Risk Level: Surface:	V - Very Low Risk Sand	
J.				
to the second				
	the second second			
Finding: The surface has eroded and the foundations are exposed		Action: Reinstate surrounding surfaces to cover the foundations		
6 - Low Ris	sk (Finding 2)			
ltem: Manufacturer:	Ancillary Items - Bench Not Identified	Risk Level: Surface:	L - Low Risk Sand	
	All and all and a second	der a	Caller Contraction	
A Second				
	a stand for the stand of the	1 1 1 1 1	THE ARE AND A MAN	
	A start and a start and a start	And the second	and the second	

Finding: A number of fixing(s) have worked loose

Action: Secure all loose fixings





Finding: There are a number of loose posts around the fence

Action: Monitor for any further deterioration and reset as required



5 - Very Low Risk (Finding 1)

 Item:
 Swings - Single Point Swing - Type 3
 Risk Level:
 V - Very Low Risk

 Manufacturer:
 Not Identified
 Surface:
 Sand

Finding: The chain openings are in excess of the 8.6mm as **Action:** Monitor - No remedial work recommended recommended by BS EN 1176

6 - Low Risk (Finding 2) Item: Swings - Single Point Swing - Type 3 Manufacturer: Not Identified Risk Level: L - Low Risk Surface: Sand

Finding: There is some notable evidence of connecting link wear **Action:** Monitor for any further deterioration and replace when 40% worn



6 - Low Risk (Finding 3)


Swings - Single Point Swing - Type 3 Item: Manufacturer: Not Identified

Risk Level: Surface:

L - Low Risk Sand

Finding: There is some notable evidence of chain wear

Action: Monitor for any further deterioration and replace when 40% worn



Finding: The bushes are worn or missing

Action: Replace worn or missing bushes




12 - Moderate Risk (Finding 5)

Swings - Single Point Swing - Type 3 Item: Not Identified Manufacturer:

Risk Level: Surface:

M - Moderate Risk





Finding: This item has an internal failsafe to catch the universal joint in the event of a catastrophic failure, however components as necessary as the failsafe is internal, the equipment is of some age and also due to its highly dynamic nature, we would recommend that the item is stripped down and a replacement provided as necessary.

Action: Strip down the universal joint and replace any worn

6 - Low Risk (Finding 6)

Item: Manufacturer:

Swings - Single Point Swing - Type 3 Not Identified

Risk Level: Surface: Sand

L - Low Risk



Finding: There are sharp projections on the split pins

Action: Remove projections



6 - Low Risk (Finding 7)

Swings - Single Point Swing - Type 3 Item: Manufacturer: Not Identified

Risk Level: Surface:

L - Low Risk Sand



Finding: The swing seat connectors have some wear present



40% worn

8 - Low Risk (Finding 8)

space

Item: Swings - Single Point Swing - Type 3 Risk Level: L - Low Risk Not Identified Surface: Sand Manufacturer: Finding: The adjacent foliage is overgrowing the falling Action: Cut back and maintain



😭 8 - Low Risk (Finding 1)

Item: Manufacturer:

Swings - 1 Bay 3 Seat (Cradle) Record RSS

Risk Level: Surface:

L - Low Risk Sand



Finding: The frame is bent

Action: Monitor for any further deterioration and replace when worn



5 - Very Low Risk (Finding 2)

Item: Manufacturer:

Swings - 1 Bay 3 Seat (Cradle) Record RSS

Risk Level: Surface:

V - Very Low Risk Sand

L - Low Risk



Finding: The chain openings are in excess of the 8.6mm as Action: Monitor - No remedial work recommended recommended by BS EN 1176

6 - Low Risk (Finding 3) Item: Swings - 1 Bay 3 Seat (Cradle) **Risk Level:** Manufacturer: Record RSS



Finding: There are caps missing from the underside of the Action: Replace missing caps under the seats seats



6 - Low Risk (Finding 4)

Item: Manufacturer:

Item:


Swings - 1 Bay 3 Seat (Cradle) Record RSS

Risk Level: Surface:

L - Low Risk Sand



Finding: There is some notable evidence of chain wear



6 - Low Risk (Finding 5) Swings - 1 Bay 3 Seat (Cradle) Risk Level: L - Low Risk Manufacturer: Record RSS Surface: Sand



Finding: The seats are too close to each other as defined in Action: Monitor - No remedial work recommended BS EN 1176 Part 2; this is a low risk failure and no remedial action is required



4 - Very Low Risk (Finding 6)

Item: Swings - 1 Bay 3 Seat (Cradle) Manufacturer: Record RSS Risk Level: Surface: V - Very Low Risk Sand



Finding: The seats are too close to the frame as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required

8 - Low Risk (Finding 7)

Item: Swings - 1 B Manufacturer: Record RSS

Swings - 1 Bay 3 Seat (Cradle)

Risk Level: L Surface: Sa

L - Low Risk Sand



Finding: There are more than 2 seats in a single bay in contravention of BS EN 1176

Action: Monitor use and remove the middle swing if required



👔 8 - Low Risk (Finding 1)

ltem: Manufacturer:

Swings - 1 Bay 3 Seat (Flat) Record RSS Risk Level: Surface:





Finding: There are more than 2 seats in a single bay in contravention of BS EN 1176

Action: Monitor use and remove the middle swing if required

5 - Very Low Risk (Finding 2)

Item: Manufacturer:

Swings - 1 Bay 3 Seat (Flat) Record RSS Risk Level: Surface: V - Very Low Risk Sand



Finding: The chain openings are in excess of the 8.6mm as **Action:** Monitor - No remedial work recommended recommended by BS EN 1176



6 - Low Risk (Finding 3)

Item: Manufacturer: Swings - 1 Bay 3 Seat (Flat) Record RSS

Risk Level: Surface: L - Low Risk Sand



Finding: There is some notable evidence of chain wear

Action: Monitor for any further deterioration and replace when 40% worn



Finding: The seats are too close to the frame as defined in **Action:** Monitor - No remedial work recommended BS EN 1176 Part 2; this is a low risk failure and no remedial action is required



8 - Low Risk (Finding 5)

Item: Swings - 1 Manufacturer: Record RS

Swings - 1 Bay 3 Seat (Flat) Record RSS

Risk Level: Surface: L - Low Risk Sand



Finding: The seats are too close to each other as defined in **Action:** Consider removing the middle seat BS EN 1176 Part 2; this is a low risk failure and no remedial action is required

5 - Very Low Risk (Finding 1)

Item: Manufacturer: Other - Wooden Animal Not Identified

Risk Level: Surface: V - Very Low Risk Sand




Finding: The bench forms a projecting obstacle / hard object within the falling space of the equipment, in contravention of the requirements of BS EN 1176 Part 1



Action: Monitor - No remedial work recommended





Finding: The large rocks / firepit forms a projecting obstacle **Action:** Remove all stones, rocks and other debris from the falling space of the equipment, in contravention of the requirements of BS EN 1176 Part 1




4 - Very Low Risk (Finding 2)





8 - Low Risk (Finding 3)



Finding: This item has no slide bar fitted as required by BS **Action:** Monitor - No remedial work recommended EN 1176 Part 3



4 - Very Low Risk (Finding 4)

Item:Activity Equipment - Multi Play (Junior)Risk Level:V - Very Low RiskManufacturer:Not IdentifiedSurface:Sand



Finding: There is/are inserts missing

Action: Replace missing inserts

💮 8 - Low Risk (Finding 5)




Finding: There is or are fixings missing on the item

Action: Replace all missing fixings




5 - Very Low Risk (Finding 6)



Finding: The item fails to meet the requirements of BS EN **Action:** Monitor - No remedial work recommended 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps




6 - Low Risk (Finding 7)



corroding




8 - Low Risk (Finding 8)





6 - Low Risk (Finding 9)



Finding: There is an opening in the barriers exceeding the width allowed (500mm) in BS EN 1176, and no guardrail has been provided; this is a low risk failure and no remedial action is required



10 - Low Risk (Finding 10)



Finding: There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176 Part 1; 4.2.8.4



6 - Low Risk (Finding 11)


Activity Equipment - Multi Play (Junior) **Risk Level:** L - Low Risk Item: Manufacturer: Not Identified Surface: Sand

Finding: The vegetation forms a hard object within the falling space of the equipment and there is also insufficient surfacing provided in contravention of BS EN 1176 Part 1

Action: Monitor - no remedial work recommended



6 - Low Risk (Finding 12)




Finding: A number of fixing(s) have worked loose

Action: Secure all loose fixings




6 - Low Risk (Finding 13) 8



structure that have rotted



5 - Very Low Risk (Finding 14)



Finding: There is/are finger entrapment/s in the framework **Action:** Replace missing inserts to remove entrapments and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers



😭 8 - Low Risk (Finding 15)



Finding: The design of the barrier does not prevent a user from passing underneath in contravention of the requirements of BS EN 1176 Part 1

Action: Monitor use and provide a compliant barrier as required



4 - Very Low Risk (Finding 16)

Item:Activity Equipment - Multi Play (Junior)Risk Level:Manufacturer:Not IdentifiedSurface:

V - Very Low Risk Sand



Finding: There is insufficient guarding on the steps leading **Action:** Monitor - No remedial work recommended up to the platform that exceeds 1m in height which contravenes the requirements on BS EN 1176 Part 1

8 - Low Risk (Finding 17)

 Item:
 Activity Equipment - Multi Play (Junior)
 Risk Level:
 L - Low Risk

 Manufacturer:
 Not Identified
 Surface:
 Sand