Improvement and Prohibition Enforcement Notices

Date served	Type of Notice	Reason
07/01/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site
08/01/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site
20/01/2021	Improvement	Failure to inspect and maintain the electrical installation in an engineering workshop
20/01/2021	Improvement	Failure to provide adequate welfare facilities in an engineering workshop
20/01/2021	Improvement	Failure to have a pressure vessel inspected under a written scheme of examination in a welding workshop
22/01/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site
26/01/2021	Improvement	Failure by a worker in a food and drink premises to wear a face mask or visor when in the presence of visitors
28/01/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site
29/01/2021	Improvement	Failure to provide adequate welfare facilities on a construction site
08/02/2021	Prohibition	Unsafe work at height on a construction site
10/02/2021	Improvement	Failure to assess and control vehicle and pedestrian segregation at a workplace
22/02/2021	Prohibition	Risk of falls though incomplete scaffold
02/03/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site
09/03/2021	Prohibition	Failure to close a business premises when being open to the public was prohibited under Covid-19 legislation
09/03/2021	Prohibition	Failure by a barber, as a worker in a close contact services premises, to wear a face mask or visor when in the presence of visitors

11/03/2021	Prohibition	Failure by a worker in a food and drink premises to wear a face mask or visor when in the presence of visitors
22/03/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site, including a failure to provide adequate welfare facilities
29/03/2021	Improvement	Failure to prepare a written safe work method statement for work with asbestos
30/03/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site, including a failure to provide adequate welfare facilities
28/04/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 on a construction site, including a failure to provide adequate welfare facilities
29/04/2021	Prohibition	Unsafe work at height on a construction site
29/04/2021	Prohibition	Inadequate arrangements to minimise the spread of Covid- 19 in a hospitality premise
22/06/2021	Improvement	Failure to assess and implement a safe system of work for the operation of a towing trailer in a marine engineering workshop
23/07/2021	Prohibition	Unsafe work at height on a construction site
06/08/2021	Improvement	Failure to reduce exposure to wood dust in a joinery workshop
06/09/2021	Improvement	Failure to provide adequate welfare facilities on a construction site
09/09/2021	Improvement	Failure to provide adequate welfare facilities on a construction site
09/09/2021	Prohibition	Unsafe excavation on a construction site
22/09/2021	Prohibition	Unsafe work at height on a construction site