

Victoria Avenue Cycle Promenade



Inspection and Maintenance Information


2018

Inspections

Routine and reactive maintenance inspections where undertaken to determine the condition of the surface and to log intervention level defects to be repaired or monitored for future repair.

Inspections of the Victoria Avenue Cycle Track Promenade where carried out on the following dates:

- 18 October 2018 (Routine)
- 26 July 2018 (Routine)
- 03 May 2018 (Routine)
- 05 November 2017 (Reactive)



ID	Name	Inspector	Status	Scheduled	Started	Suspended	Resumed	Completed
366	Avenue Cycle Track		Completed	03/05/2018	24/07/2018			25/07/2018
480	Avenue Cycle Track		Completed	26/07/2018	08/08/2018			08/08/2018
498	Avenue Cycle Track		Completed	18/10/2018	10/10/2018			10/10/2018

Maintenance Jobs in 2018

Job Reference H059860

Job Registration
HIGHWAYWORKS

Reference:
 Inspector Name:


Job Priority:
 Contractor:

Title:
 Supervisor:
 Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Potholes	Cycleway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H059860-D1		20171207_091122_SH M2.jpg	20171207_091123_SH M2.jpg

Registration Close-Up



Registration Overview



Job Reference H069025

Job Registration
HIGHWAYWORKS

Reference:
 Inspector Name:


Job Priority:
 Contractor:

Title:
 Supervisor:
 Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Potholes	Cycleway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H069025-D1		20180825_111050_SH M2.jpg	

Registration Close-Up



Registration Overview



Job Reference H069021

Job Registration
HIGHWAYWOR

Reference:
 Inspector Name:

Job Priority:
 Contractor:


Title:
 Supervisor:

Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Depression	Cycleway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H069021-D1		20180826_110942_SH M2.jpg	

Registration Close-Up



Registration Overview



Job Reference H068329

Job Registration
HIGHWAYWOR

Reference:
 Inspector Name:

Job Priority:
 Contractor:


Title:
 Supervisor:

Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Ironwork / Surround Defective	Carriageway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H068329-D1		20180726_133046_SH M2.jpg	

Registration Close-Up



Registration Overview



Job Reference H069020

Job Registration
HIGHWAYWOR

Reference:
 Inspector Name:

Job Priority:
 Contractor:


Title:
 Supervisor:

Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Potholes	Cycleway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H069020-D1		20180826_111424_SH M2.jpg	

Registration Close-Up



Registration Overview



Job Reference H069655

Job Registration
HIGHWAYWOR

Reference:
 Inspector Name:

Job Priority:
 Contractor:


Title:
 Supervisor:

Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Depression	Cycleway	Yes
2 - Other	Cycleway	Yes
3 - Ponding / Standing Water	Cycleway	Yes
4 - Ponding / Standing Water	Cycleway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H069655-D1		20181122_084840_JR DR.jpg	
H069655-D2		20181122_084840_JR DR_2.jpg	
H069655-D3		20181122_084840_JR DR_3.jpg	

Registration Close-Up



Registration Overview



Job Reference H071378

Job Registration
HIGHWAYWORKS

Reference:
 Inspector Name:

Job Priority:
 Contractor:


Title:
 Supervisor:

Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Depression	Cycleway	Yes

Defect - Close-Up




Defect - Overview




Registration(s):

Ref	Details	Close-Up	Overview
H071378-D1		20180926_140827_SH M2.jpg	20180926_140828_SH M2.jpg

Registration Close-Up



Registration Overview



Job Reference H069718

Job Registration
HIGHWAYWORKS

Reference:
 Inspector Name:

Job Priority:
 Contractor:


Title:
 Supervisor:

Completed:


Defect(s) - Items still to register: 0

Defect	Position	Register...
1 - Potholes	Cycleway	Yes

Defect - Close-Up




Defect - Overview



Registration(s):

Ref	Details	Close-Up	Overview
H069718-D1		20181122_084903_JR DR.jpg	

Registration Close-Up



Registration Overview

